

Appendix C

Factflash Directory

This Appendix contains a list of ALL factflashes that should be currently filed with your DATADOC. Any factflash that is not listed here is out of date and should be thrown away.

All Factflashes have filing instructions, and most go with one of the DATADOC chapters. Any factflashes that have no more suitable "home" are filed with this appendix.

C.1 Index of Factflashes in Datadoc

Date	Title	Filing Instructions
15-Feb-1993	6500 forms incorrect Shadow Set Number	End of Chapter 1, VAX 6000 CALYPSO series
22-Apr-1994 ✓	6000 series, consol revision matrix	End of Chapter 1, VAX 6000 CALYPSO series
7-Feb-1995 ✓	6000 series, consol revision matrix	End of Chapter 1, VAX 6000 CALYPSO series
24-May-1994 ✓	Nautilus Consoles at Welwyn/Newmarket	End of Chapter 2, VAX88x0/8700/85x0
22-Dec-1993 ✓	VAX 7000 FCO warning	End of Chapter 6, DEC/VAX 7xx0/10xx0
23-Mar-1994 ✓	CCL Interconnect Diagram	End of Chapter 6, DEC/VAX 7xx0/10xx0
20-Sep-1994 ✓	Locating Bad Chips	End of Chapter 6, DEC/VAX 7xx0/10xx0
1-May-1995 ✓	Introducing Alphaserpver 8400 and 8200	End of Chapter 6, DEC/VAX 7xx0/10xx0
28-Nov-1991	Devices not logging errors	End of Chapter 7, VMS
15-Dec-1991	Roo-Roo bits, VMS 5.4-3 Rel Notes	End of Chapter 7, VMS
2-Jan-1992	Vax Vms 5.5, Digital Services Advisory	End of Chapter 7, VMS
15-Jan-1992	Fsterr	End of Chapter 7, VMS
16-Sep-1993 ✓	Useful VMS commands for T/S	End of Chapter 7, VMS
22-Dec-1993 ✓	Backup Verify, Analyse/disk errors	End of Chapter 7, VMS
6-May-1994 ✓	Backup Quotas - SCSI problems	End of Chapter 7, VMS
20-May-1994 ✓	Can't see MSCP devices under VMS	End of Chapter 7, VMS
6-May-1994 ✓	VMS Ver 6.x doesn't autosize memory	End of Chapter 7, VMS
10-May-1994 ✓	VMS 6.1 now VAX and AXP Compatible	End of Chapter 7, VMS
2-May-1995 ✓	OpenVMS 6.2 - New Features	End of Chapter 7, VMS
15-May-1987	Diagnostic OKDA failures	End of Chapter 9, PDP11
9-Feb-1988 ✓	FCO to fix "random" errors (1183 /1184)	End of Chapter 9, PDP11
10-Apr-1990 ✓	11-84 LTC failure	End of Chapter 9, PDP11
10-Sep-1990 ✓	New processor 1193/4 KDJ11-E	End of Chapter 9, PDP11
27-Nov-1990 ✓	Part no's for 11/84E PSU	End of Chapter 9, PDP11

Date	Title	Filing Instructions
20-Jan-1989	Reasons to be careful	End of Chapter 10, VAXclusters
14-Oct-1992	Brief overview of cluster revisions	End of Chapter 10, VAXclusters
17-Feb-1993	SDD Version 2.0 is here	End of Chapter 11, VAXsimPLUS(SDD)
15-Jun-1993 ✓	Tricom 10/42 (AES) Modem setup	End of Chapter 11, VAXsimPLUS(SDD)
7-Sep-1993 ✓	VaxsimPlus Repair Log	End of Chapter 11, VAXsimPLUS(SDD)
23-Jan-1995 ✓	VAXPAX 53, 54, 55 and 56 release notes	End of Chapter 12, Diagnostics
15-Apr-1993	DEC 3000 Model 400 Plastic Washers	End of Chapter 13, DEC 3000 AXP
13-Sep-1990	MDM 130/131 boot failures	End of Chapter 14, QBUS SYSTEMS
16-Mar-1993 ✓	Creating MDM Tapes - (at Welwyn)	End of Chapter 14, QBUS SYSTEMS
6-May-1994 ✓	New upgrade for BA200/400	End of Chapter 14, QBUS SYSTEMS
10-May-1994	New FW for 4100, 4100A, 3100-90	End of Chapter 14, QBUS SYSTEMS
2-Oct-1989	3100 hangs after dismounting a tape	End of Chapter 15, DESKTOP SYSTEMS
10-Feb-1992	VS4000 Model 60 LCG Modules unseat	End of Chapter 15, DESKTOP SYSTEMS
3-Mar-1992	DECSystem 5000 FIS Patch	End of Chapter 15, DESKTOP SYSTEMS
2-Nov-1992	5240, 5900 Poss. Data Corruption	End of Chapter 15, DESKTOP SYSTEMS
3-Nov-1992	Bootting KZQSA disks on 2nd KZQSA	End of Chapter 15, DESKTOP SYSTEMS
3-Feb-1993 ✓	System Module Revision Problem etc.	End of Chapter 15, DESKTOP SYSTEMS
23-Aug-1993 ✓	DHW41/42 DMA problem	End of Chapter 15, DESKTOP SYSTEMS
22-Oct-1993 ✓	DSSI id setting and VMS	End of Chapter 15, DESKTOP SYSTEMS
22-Oct-1993	Bootting MDM on a 4100s TZ30	End of Chapter 15, DESKTOP SYSTEMS
22-Oct-1993 ✓	VAX 4100s with QBUS and BDCOK	End of Chapter 15, DESKTOP SYSTEMS
22-Oct-1993	DEFZA offline on VAXstation 4000-90	End of Chapter 15, DESKTOP SYSTEMS
26-Oct-1993 ✓	RZ25L/TZK10 on VAXstation 4000	End of Chapter 15, DESKTOP SYSTEMS
26-Oct-1993	TTA3 hangs on MV3100 mods 30 and 40	End of Chapter 15, DESKTOP SYSTEMS
27-Oct-1993	RF35 logging ECC/BBRs on VAX 4000-10	End of Chapter 15, DESKTOP SYSTEMS
27-Oct-1993 ✓	Memory reporting on Waverley systems	End of Chapter 15, DESKTOP SYSTEMS
22-Nov-1993 ✓	Part number wrong for KA50/52	End of Chapter 15, DESKTOP SYSTEMS
17-Dec-1993	MV3100-90 console exciser with TLZ6L	End of Chapter 15, DESKTOP SYSTEMS
21-Dec-1993	Converting VR320 from 66 to 72 Hz	End of Chapter 15, DESKTOP SYSTEMS
22-Dec-1993 ✓	Extra power cable on MV3100-80	End of Chapter 15, DESKTOP SYSTEMS
22-Dec-1993 ✓	Part Nos for ROMS - FW Ver 1.3 and 1.4	End of Chapter 15, DESKTOP SYSTEMS
5-May-1994 ✓	Tables with new VAX systems	End of Chapter 15, DESKTOP SYSTEMS
6-May-1994 ✓	VRC21 new monitor	End of Chapter 15, DESKTOP SYSTEMS
27-Dec-1990	SCSI terminators on RZ55 modules	End of Chapter 16, SMALL DEVICES
5-Feb-1993	FRU Strategy for the RZ56 and RZ57.	End of Chapter 16, SMALL DEVICES
12-Mar-1993	New Device notes on the RZ26B	End of Chapter 16, SMALL DEVICES
16-Mar-1993	Drives going offline - troubleshooting	End of Chapter 16, SMALL DEVICES
16-Mar-1993	MD400s on VAXsta 4000s fail PUST	End of Chapter 16, SMALL DEVICES
7-Apr-1993	RF31T, RF35 and RF73 FW Revs D & E	End of Chapter 16, SMALL DEVICES
18-Jun-1993 ✓	IEZ11 Offline - H/W and S/W Revisions	End of Chapter 16, SMALL DEVICES
26-Oct-1993 ✓	RZ58 problems on ULTRIX - Update	End of Chapter 16, SMALL DEVICES
27-Oct-1993	RF36 HBVS takes up to 8 hours to copy	End of Chapter 16, SMALL DEVICES
17-Dec-1993	Part No for TORX screwdriver set	End of Chapter 16, SMALL DEVICES
22-Dec-1993 ✓	Clean floppy drives before changing	End of Chapter 16, SMALL DEVICES
5-May-1994 ✓	New devices in old tables	End of Chapter 16, SMALL DEVICES
21-Sep-1994 ✓	RX Floppy Vendor Part Nos.	End of Chapter 16, SMALL DEVICES
12-Sep-1994 ✓	Current RZ26L/DSP3107 Drive Issues	End of Chapter 16, SMALL DEVICES

Feb-1988	Repaired with bootlace (DESVa)	End of Chapter 18, ETHERNET
Sep-1988	New bulb for fibre-optic torch	End of Chapter 18, ETHERNET
Sep-1988 ✓	DELQA, PDP11 support	End of Chapter 18, ETHERNET
13-Feb-1989 ✓	Barclays Bank ethernet testing	End of Chapter 18, ETHERNET
8-Jun-1990 ✓	DEBNI monitor crashing VMS	End of Chapter 18, ETHERNET
8-Oct-1990 ✓	New DELQA-PLUS option	End of Chapter 18, ETHERNET
3-Oct-1991	DEQNA retirement	End of Chapter 18, ETHERNET
Jul-1988	Incorrect DECSA fans may cause hangs	End of Chapter 19, ETHERNET_SERVERS
26-Mar-1990 ✓	DecServer 250 failure at power up	End of Chapter 19, ETHERNET_SERVERS
24-Aug-1990 ✓	DecServer 500, baud rate jumpers	End of Chapter 19, ETHERNET_SERVERS
21-Apr-1989 ✓	LP27 paper feed idler bearings	End of Chapter 23, Printers
28-Mar-1990 ✓	New LG ribbon assembly	End of Chapter 23, Printers
24-Dec-1991	LPS40 Fuser oil tray overflows	End of Chapter 23, Printers
3-Mar-1992	New Fusers for the LPS20	End of Chapter 23, Printers
5-Jun-1992	Faulty LG06 Control Panels.	End of Chapter 23, Printers
9-Jun-1992	LG06 Paper Loading.	End of Chapter 23, Printers
17-Jun-1992	Fix for LPS20 Turbo Hang Problems.	End of Chapter 23, Printers
17-Jun-1992	LXY printers cannot use flow control	End of Chapter 23, Printers
21-Aug-1992	Two Firmware fixes for the LPS20 Turbo.	End of Chapter 23, Printers
2-Nov-1992	LG06 sticking hammers	End of Chapter 23, Printers
17-Dec-1992	LPS20 Fusers from Nijmegen	End of Chapter 23, Printers
18-Dec-1992	LPS20 wrinkling paper in duplex mode	End of Chapter 23, Printers
7-Apr-1993 ✓	Output tray of LPS32 now for LPS20	End of Chapter 23, Printers
18-Jun-1993 ✓	LPS32 New IPB available	End of Chapter 23, Printers
26-Jun-1993 ✓	LG31 shipping brackets	End of Chapter 23, Printers
23-Aug-1993 ✓	12 MB for LPS17 Duplex Printing	End of Chapter 23, Printers
14-Sep-1993 ✓	LG06 shuttle and ink migration problems	End of Chapter 23, Printers
17-Sep-1993 ✓	LG31 bits of characters missing	End of Chapter 23, Printers
27-Oct-1993 ✓	LPS17 Controller FW revision	End of Chapter 23, Printers
27-Oct-1993 ✓	"Replace OPD Drum" message	End of Chapter 23, Printers
29-Oct-1993 ✓	LG12 - A New Printer	End of Chapter 23, Printers
22-Dec-1993 ✓	Grooves on paper using LPS17	End of Chapter 23, Printers
22-Dec-1993 ✓	Functionality of new LA310 firmware	End of Chapter 23, Printers
22-Dec-1993 ✓	LA424 Firmware V4.0 compatibility	End of Chapter 23, Printers
19-Jan-1994	LG06 New Maintenance Manual	End of Chapter 23, Printers
14-Feb-1994 ✓	DEClaser 1152, 1152+, 1252 and 1252+	End of Chapter 23, Printers
14-Feb-1994 ✓	Printer hoods supplied by DECdirect	End of Chapter 23, Printers
18-Feb-1994 ✓	Change in customer consumable kits	End of Chapter 23, Printers
16-May-1994 ✓	Table of laser printers and attributes	End of Chapter 23, Printers
30-Jan-1995 ✓	LXYxx/P300/600 Safety Issue - Revised	End of Chapter 23, Printers
30-Mar-1995 ✓	PL111 - Cost Relief	End of Chapter 26, FCO Information
2-May-1995 ✓	New FCOs for 1995	End of Chapter 26, FCO Information
17-Dec-1985	Running EVDLC on Emulex CC11/CS11	End of Chapter 27, VES
7-Jan-1986	Emulex CS21/F1, CS11/F	End of Chapter 27, VES
20-Apr-1990	Cipher M990 Rev 11 firmware and pcb	End of Chapter 27, VES
20-Sep-1990	CDC 9762/6 DOA option swaps	End of Chapter 27, VES
31-Jan-1991	Exabyte issues	End of Chapter 27, VES
6-Sep-1991	Exabyte on SCSI A or B of 3100	End of Chapter 27, VES
11-Mar-1993	Power Supply requirements and T/S	End of Chapter 27, VES
11-Mar-1993	Power Supply T/S, Always have a load	End of Chapter 27, VES
7-Apr-1993	CMD QBus to SCSI controllers	End of Chapter 27, VES
22-Oct-1993 ✓	Support for Emulex with VMS V6.0	End of Chapter 27, VES
27-Oct-1993 ✓	Lion Enclosures - 50 watt PSUs	End of Chapter 27, VES

Date	Title	Filing Instructions
1-Nov-1993 ✓	Compatibility, Non-DEC SCSI disks	End of Chapter 27, VES
22-Dec-1993 ✓	FW problems with CMD controllers	End of Chapter 27, VES
28-Sep-1992	Return of Loan parts	End of Appendix B, Logistics
8-Sep-1986	3 Phase Power Connectors	End of Appendix C, Factflash Directory
19-May-1987	Problems with KDB50 FCO	End of Appendix C, Factflash Directory
Nov-1987	KMS11-BD cable installation	End of Appendix C, Factflash Directory
21-Jan-1988	SAFETY FCO (1178x, 86x0)	End of Appendix C, Factflash Directory
19-Feb-1988	Dot matrix characters squashed	End of Appendix C, Factflash Directory
Aug-1988	VMS 5.0 and modem control	End of Appendix C, Factflash Directory
23-Sep-1988	DVM gives false reading	End of Appendix C, Factflash Directory
Sep-1988	DEC RS423 receiver chip problem	End of Appendix C, Factflash Directory
1-Nov-1988	LP11 Jumpers	End of Appendix C, Factflash Directory
31-Jan-1989 ✓	DEC432 Problems Part 2	End of Appendix C, Factflash Directory
31-Jan-1989 ✓	DMV11 Switches	End of Appendix C, Factflash Directory
31-Jan-1989 ✓	X.21 cable problems	End of Appendix C, Factflash Directory
28-Mar-1989 ✓	DSV11 Bad DMA chip	End of Appendix C, Factflash Directory
7-Jun-1989 ✓	Using and installing the Dranetz	End of Appendix C, Factflash Directory
13-Jul-1989 ✓	CSRs & vectors on KMV11s	End of Appendix C, Factflash Directory
2-Mar-1990 ✓	Rdc modems revisited again	End of Appendix C, Factflash Directory chapter 11
21-Jun-1990	Faulty BC16E cables	End of Appendix C, Factflash Directory
28-Jun-1990	Cable making kit	End of Appendix C, Factflash Directory
6-Sep-1990 ✓	Fuse part numbers	End of Appendix C, Factflash Directory
20-Sep-1990	DEBNAs, DEBNIs, and FCO 62XMX	End of Appendix C, Factflash Directory
15-Jan-1992	Fan part numbers	End of Appendix C, Factflash Directory
1-May-1992	Useful RSX crash info and commands.	End of Appendix C, Factflash Directory
9-Feb-1994 ✓	DEC 2000 and DEC 4000 AXP systems	End of Appendix C, Factflash Directory
9-Aug-1994 ✓	End of Service Life - Products	End of Appendix C, Factflash Directory
30-Jan-1995 ✓	Tbols and General Part Numbers	End of Appendix C, Factflash Directory