

# **HP FDDI/9000 Release Notes**

## **HP 9000 Networking**



**Manufacturing Part Number: J2157-90052  
E0999**

United States

© Copyright 1998 Hewlett-Packard Company.

---

## Legal Notices

The information in this document is subject to change without notice.

*Hewlett-Packard makes no warranty of any kind with regard to this manual, including, but not limited to, the implied warranties of merchantability and fitness for a particular purpose.* Hewlett-Packard shall not be held liable for errors contained herein or direct, indirect, special, incidental or consequential damages in connection with the furnishing, performance, or use of this material.

**Warranty.** A copy of the specific warranty terms applicable to your Hewlett-Packard product and replacement parts can be obtained from your local Sales and Service Office.

**Restricted Rights Legend.** Use, duplication or disclosure by the U.S. Government is subject to restrictions as set forth in subparagraph (c) (1) (ii) of the Rights in Technical Data and Computer Software clause at DFARS 252.227-7013 for DOD agencies, and subparagraphs (c) (1) and (c) (2) of the Commercial Computer Software Restricted Rights clause at FAR 52.227-19 for other agencies.

HEWLETT-PACKARD COMPANY  
3000 Hanover Street  
Palo Alto, California 94304  
U.S.A.

Use of this manual and flexible disk(s) or tape cartridge(s) supplied for this pack is restricted to this product only. Additional copies of the programs may be made for security and back-up purposes only. Resale of the programs in their present form or with alterations, is expressly prohibited.

**Copyright Notices.** ©copyright 1983-99 Hewlett-Packard Company, all rights reserved.

Reproduction, adaptation, or translation of this document without prior written permission is prohibited, except as allowed under the copyright laws.

©copyright 1979, 1980, 1983, 1985-93 Regents of the University of California

This software is based in part on the Fourth Berkeley Software Distribution under license from the Regents of the University of

California.

©copyright 1980, 1984, 1986 Novell, Inc.

©copyright 1986-1992 Sun Microsystems, Inc.

©copyright 1985-86, 1988 Massachusetts Institute of Technology.

©copyright 1989-93 The Open Software Foundation, Inc.

©copyright 1986 Digital Equipment Corporation.

©copyright 1990 Motorola, Inc.

©copyright 1990, 1991, 1992 Cornell University

©copyright 1989-1991 The University of Maryland

©copyright 1988 Carnegie Mellon University

**Trademark Notices** UNIX is a registered trademark of The Open Group.

X Window System is a trademark of the Massachusetts Institute of Technology.

MS-DOS and Microsoft are U.S. registered trademarks of Microsoft Corporation.

OSF/Motif is a trademark of the Open Software Foundation, Inc. in the U.S. and other countries.



---

# Contents

## 1. HP FDDI/9000 Release Notes

HP-UX Version B.10.20.09 .....	9
What's in this Version? .....	9
Known Problems and Workarounds for this version .....	9
Compatibility Information and Installation Requirements .....	9
Patches for this version .....	10
HP-UX Version 11.00.05 .....	11
What's in this version? .....	11
Known Problems and Workarounds for this version .....	11
Compatibility Information and Installation Requirements .....	11
Fixes in this version .....	13

---

# Contents

---

# **1 HP FDDI/9000 Release Notes**

The following information is for version *B.10.20.09* of HP FDDI/9000, for servers (product numbers *J2157B*, *J2658BA* and *J2658AA\_APZ*) and for workstations (product numbers *A2654A* and *A2665A*).

## HP FDDI/9000 Release Notes

It also contains information for version *B.11.00.05* of HP FDDI/9000 (product numbers *J2157B* and *J2658BA*).



## **HP-UX Version B.10.20.09**

### **What's in this Version?**

The following sections describe the 10.20.09 version of HP FDDI/9000 for servers and for workstations.

#### **Fixes**

There have been no new fixes since the previous release.

### **Known Problems and Workarounds for this version**

There are no known problems with this version of HP FDDI/9000.

## **Compatibility Information and Installation Requirements**

### **Software Requirements**

- HP-UX 10.20 operating system

### **Hardware Requirements**

For HP-UX 10.20 and later versions:

- HP 9000 Servers with HP-PB Bus

This version of HP FDDI/9000 can only be installed on platforms that have an HP-PB bus. The platforms are: HP 9000 Series 800 Models E, G, H, I, K, and T.

- CD-ROM drive to install/update media

### **Memory and Disk Space Requirements**

- 16 MB memory
- 1 MB free disk space

### **Install/Upgrade With System Up or Down**

- One reboot is required for installation and configuration
- Super user mode is required

### **Installing and Upgrading HP FDDI/9000**

The *Installing and Administering HP FDDI/9000* manual (J2157-90013) contains complete instructions for installing this product. Refer to this document for more information.

### **Patches for this version**

For the IP Multicast feature, available in version 10.20.06 and above, to work properly PHNE\_14634 (or a cumulative patch superseding it) must be installed on the system.

## **HP-UX Version 11.00.05**

### **What's in this version?**

The following describes the 11.00.05 version of HP FDDI/9000 for servers.

#### **Features**

The FDDI driver can be installed on both 64-bit and 32-bit HP-UX 11.00 OS.

#### **Fixes**

Some fixes were incorporated into this release of HP FDDI/9000. See the section “Fixes in this Version” for more information.

### **Known Problems and Workarounds for this version**

There are no known problems with this version of HP FDDI/9000.

## **Compatibility Information and Installation Requirements**

### **Software Requirements**

- HP-UX 11.00 operating system

### **Hardware Requirements**

- HP 9000 Series 800 Models with HP-PB Bus

This version of HP FDDI/9000 can only be installed on platforms that have an HP-PB bus. The platforms are: HP 9000 Series 800 Models E, G, H, I, K, and T.

- Install/update media hardware, such as:
  - DDS tape drive
  - CD-ROM drive

## Memory and Disk Space Requirements

- 16 MB memory
- 1 MB free disk space

## Install/Upgrade With System Up or Down

- One reboot is required for installation and configuration.
- Super user mode is required.

## Installing and Upgrading HP FDDI/9000

The *Installing and Administering HP FDDI/9000* manual (J2157-90013) and the *HP FDDI/9000 Installation and Configuration* card (J2157-90044) contain complete instructions for installing this product. Refer to this document for more information.

## Nuisance Message during installation of the product

Users may encounter a warning message in the `swinstall.log` file when the J2157B bundle is selected for installation using `'swinstall'`. This warning should be ignored.

The warning message on a 64-bit Operating System may look like this:

WARNING:       The software specification "J2157B" refers to a bundle (or to product, subproduct or fileset within a bundle). Only some of the software specified could be selected. The messages below show those items which could not be selected and those items which were selected but generated a warning:

\* Could not apply the software selection  
"FDDI-KRN-COM.FDDI467-KRN,r=B.11.00.02,a=HP-UX\_B.11.00\_32/64,v=HP,fa=HP-UX\_B.11.00\_32"  
because there are no product variations that are compatible with the destination host(s).

\* Could not apply the software selection  
"FDDI-MASTER-COM.FDDI-MASTER,r=B.11.00.03,a=HP-UX\_B.11.00\_32/64,v=HP,fa=HP-UX\_B.11.00\_32"  
because there are no product variations that are compatible with the destination host(s).

\* Could not apply the software selection

“FDDI67-KRN.FDDI-KRN,r=B.11.00.03,a=HP-UX\_B.11.00\_32/64,v=HP,fa=HP-UX\_B.11.00\_32” because there are no product variations that are compatible with the destination host(s).

### **Fixes in this version**

The defect fixes since the last release (11.00.04) are:

- The '*mk\_kernel*' was failing for HP-PB FDDI driver on some C-Class 700 series machines with 64 bit Operating Systems. This has been fixed.
- HP-PB FDDI subsystem was not being configured for *NetTL* logging and tracing under some circumstances. This has been fixed.